

Shop Equipment, Welding: Field Maintenance. This Set Is Pending Obsolescence.

SC: 4940-95-B19
NSN: 4940-00-357-7268
LIN: T16714
TM: 9-3431-258-14&P

System Description

This Set Is Pending Obsolescence.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.
- Service SKO IAW TM to 10/20 (annual service) and LO.
- Service prime mover/trailer IAW platform guidance.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil